

Frost Inc. 2020 Bristol NW Grand Rapids MI, 49504 USA



Automotive





catalog number: FTCWAutomotiveRevA

telephone: +1.800.783.6633 | fax: +1.616.453.2161 | www.frostinc.com | frost.sales@frostinc.com

telephone: +1.800.783.6633 | fax: +1.616.453.2161 | www.frostinc.com | frost.sales@frostinc.com

Remote Mounted Display Highly Precise Measurements

Runne

Lasers are programed to measure set distances between the links of the chain. This data is stored in the control box and a new cycle of data begins once the chain has completed its cycle. The recording of information can be perpetual. As long as the conveyor is running, the chain wear monitor is capturing useful data.

The CATS Benefits for Automotive

- Universal Fit. It is designed to operate inside any automotive factory in the world, independent of any existing control systems, on almost any chain design.
- Efficient. No dedicated computer is required to monitor your conveyor.
- Flexible. Data is stored internally and can be accessed multiple ways based on your needs. Data retrieval options include:
 - Through your existing network;
 - By removing the internal USB thumb drive;
 - By cell phone or tablet as you walk across your shop floor via a WiFi connection (optional feature);
 - Through the internet when equipped with a cellular modem.
- Constant Attention. The CATS system monitors your chain for wear 24 hours per day, 7 days a week, 365 days per year. If the chain is moving, we are collecting and logging data.
- Accurate. Measurements are accurate within 0.02".
- Simple to Use. All data is interpreted through an Excel spreadsheet (via a macro). The user adjusts the parameters of the report to flag links for inspection or replacement to any range they are comfortable with.
- Easy to Operate. Touch screen interface is standard.
- Remote Monitoring Available. We monitor your conveyor for you.

What kind of chain does it

work on? The Frost Chain wear monitor is currently installed in many plants, mostly on typical X-type conveyor chain. It is compatible with almost any type chain. A picture or drawing of your installed chain allows Frost to easily determine if there are any issues with compatibility.



Multiple means for storage including USB data stick, mobile device, or a desktop computer.



	4	Total # of Links:	1276	
	5	Good Links:	1274	
	6	Inspect Links:	1	
1	7	Replace Links:	1	
	8	Ideal Length:	10208.000	
	9	Actual Length:	10284.416	
	10	Replacement Length	10451.716	
	11	Percent Wear:	0.75	
	12	MIN Wear:	-0.027	
	13	MAX Wear:	0.191	
	14	AVG Wear:	0.060	
	15	Wear Change:	N/A	
	16	Percent Change:	N/A	
	47			

To read the data no special software is needed. A simple spreadsheet program will suffice.

D

List of A

Why do I need this?

As we like to say "failure is not an option." Proper utilization of the data generated by the CATS system will help prevent any catastrophic chain failures before they happen, leading to less down time and more profit for your company.

Can I buy one and set it up myself without training?

Every conveyor system is different. Our on-site installers are vital to helping you get the most out of your investment. Not only will they help your maintenance department set the unit up, but they also provide training on the use of the equipment and interpretation of the output while they are at your location.

Typical lead times are two and a half weeks for the hardware. Timing of the installation is dependent on our installer's schedules and are determined at the time of purchase.

What are the requirements? The CATS system requires a couple of things; first that the chain is moving at a steady rate most of the time. Second the chain should be clean, or mostly clean of debris.

Over time as the pins wear, the distance measured by the lasers will increase. When this occurs, the data output will indicate which links to check. In extreme circumstances, links will appear as red on the Excel spread sheet output. Red indicates the chain should be immediately replaced to avoid a costly breakdown.

	E	F	н	I.	J	К	М	Ν	0	Р	R	
List of All Links:			Links to be Inspected:				Links to be Replaced:					
ŧ	Length	Wear		Link #	Length	Wear		Link #	Length	Wear		
1	8.074	0.074		1160	8.191	0.1908		870	8.191	0.1914		
2	8.045	0.045										
3	8.057	0.057										
4	8.037	0.037										
5	8.092	0.092										
6	8.041	0.041										
7	8.011	0.011										
8	8.159	0.159										
9	8.071	0.071										
10	8.049	0.049										
11	8.007	0.007										
12	8.081	0.081										
13	8.083	0.083										
14	8.065	0.065										
45	0.040	0.040			_			_				

Customer Requirements

- Power—Dedicated 110V 10A plug.
- · Computer—Any device capable of running Microsoft (or equivalent) Excel 2003 or newer with the ability to run macros.
- Provide and install safety guards if needed.
- · Provide and install all necessary conduit if needed.